

Work Order ID 86995

86995

Page 1

July-09-12 8:11:12 AM

Item ID: D206-642-314 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Skidtube RH
 Start Date: 7/09/12 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 7/16/12 Req'd Qty: 1.00 ***1*** Customer:
 Reference: *W*

Approvals: Process Plan: *W* Date: Tooling: Date: Run Start ***NR1***
 QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D206-642	O								

100		0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Document Control	Photocopy bluefile and create labels per PPP D206-642-314		CHG001						
									<i>DAS 11 8-83 17 (09/12)</i>
									<i>12-7-20</i>
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00							
Packaging									<i>12/07/20 JB</i>
120	QC4- 100% Inspect kits for completeness	0.00							
120									
QC	Memo	0.00							
Quality Control									<i>DAS 11 8-83 8/8/10</i>

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 86995

86995

Page 2

July-09-12 8:11:12 AM

Item ID: D206-642-314

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Skidtube RH

Start Date: 7/09/12 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 7/16/12 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D206-642-314								
	Location: _____								
	PPP Rev: _____ <i>SHIP</i>								
140		0.00							
140	QC21- Final Inspection - Work Order Release								
QC	Memo	0.00							
Quality Control									

12/7/20

12/7/23

W1257.20

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:11 AM

Page 1

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH





Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00


Required Qty: 1.00

Comments: IPP REV:A 11.11.18 NEW ISSUE DD VERF:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
 D206-642-351 Replacement Skidtube		Manufactured	No		87034	110	Each	0.0000		1		87034	
 D206-648-013 GHW Modification		Manufactured	No			110	Each	6.0000		1		20	

Location Loc Qty Loc Code


FG 1
83363 1
FG120 1
65455 0
66633 0
83040 1
FG125 4
83040 2
85502 2

 D2932-2
Saddle RH Out, 206

Manufactured No 110 Each 14.0000

Location Loc Qty Loc Code

ST421 7
79224 1
81802 6
ST428 7
82135 1
83424 6

 D2933-2
Saddle RH In, 206

Manufactured No 110 Each 13.0000

Location Loc Qty Loc Code

ST421 7
81804 7
ST428 6
83425 6

85502

83424

83425

JB 12/07/20

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:11 AM

Page 2

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

D2938-2
Saddle RH Out, 206

Manufactured No

110 Each 8.0000

0

1

86424

JB

Location

Loc Qty

Loc Code

ST421

7

81806

7

ST428A

1

75102

1

D2939-2
Saddle RH In, 206

Manufactured No

110 Each 9.0000

0

1

83418

JB

Location

Loc Qty

Loc Code

ST421

7

81808

7

ST428A

2

78955

1

79238

1

AN3-41A
Bolt

Purchased No

110 Each 313.0000

8

8

Location

Loc Qty

Loc Code

ST354

313

121162

113

121243

200

121162

D2652
Bushing

Manufactured No

110 Each 195.0000

16

16

83252

JB

12/07/20

Location

Loc Qty

Loc Code

FG

44

31985

44

ST013

151

73836

36

81951

61

83744

54

July-09-12 8:11:11 AM

Shop Packet Print

Page 2

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:11 AM

Page 3

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Nut

Purchased

No

110

Each

3,318.0000

8

8

Location

Loc Qty

Loc Code

ST300

1318

117885

32

119017

771

119075

138

121444

377

ST317

2000

122141

2000

AN960JD10

Washer

NAS1149D0363J

Purchased

No

110

Each

0.0000

8

8

AN5-10A

Bolt

Purchased

No

110

Each

473.0000

4

4

Location

Loc Qty

Loc Code

ST337

473

118191

80

121243

100

122151

293

AN5-12A

Bolt

Purchased

No

110

Each

45.0000

4

4

Location

Loc Qty

Loc Code

ST338

45

121181

45

AN5-11A

Bolt

Purchased

No

110

Each

416.0000

8

8

Location

Loc Qty

Loc Code

ST337

416

118191

13

119512

403

July-09-12 8:11:11 AM

Shop Packet Print

Page 3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:11 AM

Page 4

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

AN960JD516
Washer
NAS1149D0563J
Purchased No

110 Each 12.0000

18 119546 8 ✓ JB

Location

Loc Qty

Loc Code

ST338

12

2612

12

AN4-6A
Bolt
Purchased No

110 Each 1,375.0000

12 12 - JB

Location

Loc Qty

Loc Code

ST356

1375

119017

375

121243

500

122151

500

AN960JD416
Washer
NAS1149D0463J
Purchased No

110 Each 29.0000

24 119017 122441 24 ✓ JB

Location

Loc Qty

Loc Code

ST351

29

116289

8

119097

21

MS21042L4
Nut
Purchased No

110 Each 1,401.0000

12 12 - JB 12/07/20

Location

Loc Qty

Loc Code

ST300

1401

119075

116

121011

193

121444

792

121652

300

121444

July-09-12 8:11:12 AM

Shop Packet Print

Page 4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:12 AM

Page 5

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

D3407-043

Tow Ring

Manufactured No

110 Each 4.0000

0

86919 1

JB

h

Location

Loc Qty

Loc Code

ST420

1

79232

1

ST463

3

68339

2

78841

1

D3456-1

Washer

Manufactured No

110 Each 215.0000

0

1

JB

h

Location

Loc Qty

Loc Code

FG

7

25701

7

ST044

208

80252

1

81876

15

83584

92

85223

100

83584

D3457-1

Washer

Manufactured No

110 Each 69.0000

2

2

JB

12/07/20

Location

Loc Qty

Loc Code

FG

10

32409

10

ST044

59

67779

1

81977

6

83268

12

85422

40

83268

July-09-12 8:11:12 AM

Shop Packet Print

Page 5

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:12 AM

Page 6

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

MS21043-4
Nut

Purchased No

110 Each 1,827.0000

0

1

JB h

Location

Loc Qty

Loc Code

FG 40
104603 40
ST301 787
119546 4
121162 295
121652 488
ST318 1000
122141 1000

121162

AN4C5A
BOLT

Purchased No

110 Each 172.0000

0

1

JB h

Location

Loc Qty

Loc Code

ST355 172
112243 135
119017 37

119017

AN960C416
washer

NAS1149C0463R

Purchased No

110 Each 0.0000

0

1

JB h

D3413-1
Ring

Manufactured No

110 Each 46.0000

0

1

JB 12/07/20

Location

Loc Qty

Loc Code

ST420 4
79233 4
ST464 42
80224 4
83307 18
83867 20

83307

July-09-12 8:11:12 AM

Shop Packet Print

Page 6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

July-09-12 8:11:12 AM

Page 7

Work Order ID: 86995

Parent Item: D206-642-314

Parent Item Name: Skidtube RH

Start Date: 7/09/12

Required Date: 7/16/12

Start Qty: 1.00

Required Qty: 1.00

D2712

Set Screw

Manufactured No

110 Each 631.0000

10 10

JB

Location

Loc Qty

Loc Code

FG	50	
29962	50	
ST017	581	
81871	81	81871
83559	250	
84433	250	

D2934

Saddle Spacer

Manufactured No

110 Each 77.0000

2 2

JB

G

Location

Loc Qty

Loc Code

FG	4	
31929	4	
ST021	40	
82014	40	82014
ST031	33	
85447	33	

D2935

Saddle Spacer

Manufactured No

110 Each 78.0000

2 2

JB

12/07/20

Location

Loc Qty

Loc Code

FG	6	
31793	6	
ST021	36	
78807	6	78807
82013	30	
ST031	36	
85448	36	

July-09-12 8:11:12 AM

Shop Packet Print

Page 7

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

4.5 206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -347	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
	X									D206-642-311	SKIDTUBE INSTALLATION, LH
		X								D206-642-312	SKIDTUBE INSTALLATION, RH
			X							D206-642-313	SKIDTUBE INSTALLATION, LH
				X						D206-642-314	SKIDTUBE INSTALLATION, RH
	1	1			X					D206-642-341	SKIDTUBE
						X				D206-642-347	WEARSHOE KIT (REPLACES -343)
							X			D206-642-349	RUN-ON LANDING WEARPLATE KIT
			1	1				X		D206-642-351	SKIDTUBE
	1	1	1	1					X	D206-648-013	GROUND HANDLING KIT
1					1					D2650-5	SKIDTUBE ASSEMBLY
1								1		D4361-041	SKIDTUBE ASSEMBLY
2A					14			4		D2651-1	* PLUG ⁽¹⁾
2B					14			4		D2651-3	* O-RING ⁽¹⁾
3					1			1		D2646	* AFT CAP ⁽¹⁾
4					2			2		MS27039-1-08	* SCREW ⁽¹⁾
5					2			2		NAS1149D0332J	* WASHER ⁽¹⁾ (OR AN960JD10L)
6	1		1							D2932-1	SADDLE, FWD OUT, LH
6		1		1						D2932-2	SADDLE, FWD OUT, RH
7	1		1							D2933-1	SADDLE, FWD IN, LH
7		1		1						D2933-2	SADDLE, FWD IN, RH
8	1		1							D2938-1	SADDLE, AFT OUT, LH
8		1		1						D2938-2	SADDLE, AFT OUT, RH
9	1		1							D2939-1	SADDLE, AFT IN, LH
9		1		1						D2939-2	SADDLE, AFT IN, RH
10	8	8	8	8						AN3-41A	BOLT
11	16	16	16	16						D2652	BUSHING
12A	8	8	8	8						MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8						NAS1149D0363J	WASHER (OR AN960JD10)
13	4	4	4	4						AN5-10A (OR AN5-11A)	* BOLT ⁽²⁾
14	4	4	4	4						AN5-11A (OR AN5-12A)	* BOLT ⁽²⁾
15	8	8	8	8						NAS1149D0563J	WASHER (OR AN960JD516)
16	12	12	12	12						AN4-6A	BOLT
17	24	24	24	24						NAS1149D0463J	* WASHER (OR AN960JD416)
18	12	12	12	12						MS21042-4	NUT (OR MS21042L4)
20A					6	6				D3537-1	WEARPAD (REPLACES D2643-3)
21A					1	1				D3537-3	WEARPAD (REPLACES D3429-1)
22A					1	1				D3535-11	WEARSHOE (REPLACES D2656-11)
22B					1	1				D3536-11	GASKET
23A					1	1				D3535-23	WEARSHOE (REPLACES D2656-23)
23B					1	1				D3536-23	GASKET
24A					1	1				D3535-35	WEARSHOE (REPLACES D2656-35)
24B					1	1				D3536-35	GASKET
26A					54	54				MS27039C1-08	SCREW
26B					54	54				NAS1149C0332R	WASHER (OR AN960C10L)
26C					54					ALS7-1032-130	* INSERT ⁽¹⁾ (or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
30	1	1	1	1						D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
31	1	1	1	1						D3456-1	WASHER
32	1	1	1	1						D3457-1	WASHER
33	1	1	1	1						MS21043-4	NUT
34	1	1	1	1						AN4C5A	BOLT
35	1	1	1	1						NAS1149C0463R	WASHER (OR AN960C416)
36	1	1	1	1						D3413-1	RING (REPLACES D2655)
37	10	10	10	10						D2712	SET SCREW
38	2	2	2	2						D2934	SADDLE SPACER
39	2	2	2	2						D2935	SADDLE SPACER
40									2	D3414-041	GHW LUG (REPLACES D2659)
41									4	AN3C37A	BOLT
42									8	D2652	BUSHING
43									4	MS21043-3	NUT
44									4	NAS1149C0363R	WASHER (OR AN960C10)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: 0
Date: 11.06.15

DART AEROSPACE USA, INC.

IIN-D206-642

Page 30 of 43

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -347	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
50							1	1		D4364-041	FWD WEARPLATE ASSY
51							1	1		D4364-043	AFT WEARPLATE ASSY
52							18	18		D3873-1	BUSHING
53							4			D2649	SPACER
54A							9	9		AN3-36A	BOLT
54B							9	9		NAS1149C0332R	WASHER (OR AN960C10L)
54C							9	9		MS21042-3	NUT

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D2650-5 OR D4361-041 ASSEMBLY ABOVE
 (2) CHOICE OF BOLT WILL DEPEND ON CROSSTUBE (SEE INSTALLATION PROCEDURE)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC. •
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
 OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: **O**
 Date: 11.06.15